

MISSING OUNCES - PIERSON

60008373 - 60008382 ; 60008483 - 60008490

PITARD8/25/983 Points of Head Sampler @ mill

- 1) Correctives of sampler - looking good at his time of visit to mill.
- 2) Needs to check weight of sample - if weight of sample differs - not maintaining sampler
- 3) Problem w/ Fundamental error bar is sampler because they only use 30 or 50g sample for assay which will not account for coarse gold.

DALE DEAN

- moving dump CRACK out of Pinyon.
- Have ~~DALE~~ ^{DALE} - informed w/re to special lot -

July Production - August Mining

- 0.310 Au & 3.03 oz Silver

31,625.5 tons Dry

9782.9 contained Au of
 95,695.3 " Ag

Gene Pearson -

Description of Flow Sheet on La Croya - Rock sampler

⊗ Truck Sampling -

- WHAT EVER IS AVAILABLE.

- individual samples & summary of campaign

-

- Concerned on failure to pick up slides & logs

- Come Down for